

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2026

Submitted Date:

04/21/2026

Document Number:

717300929

FIELD INSPECTION FORM

Loc ID 328138 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247800	WELL	PA	07/19/2021	GW	123-15598	CAVEY U24-2J	PA

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 247800 Type: WELL API Number: 123-15598 Status: PA Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

ECMC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (Cavey U24-2J); ECMC form 42 notice of start of plugging operations doc #402657740 received on 04/14/2021. ECMC form 42 notice of flowline abandonment completed doc #402760069 received on 07/26/2021. No flowlines/ risers observed at PA well area. Reclamation work is nearing completion/ remediation work is ongoing.

Corrective Action:

Date:

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Cavey U24-2J); ECMC form 42 notice of start of plugging operations doc #402657740 received on 04/14/2021. ECMC form 42 notice of flowline abandonment completed doc #402760069 received on 07/26/2021. No flowlines/ risers observed at PA well area. Reclamation work is nearing completion/ remediation work is ongoing.	maclarej	04/21/2026
As outlined on ECMC form 19 spill report Doc #404625011 received on 04/17/2026: While conducting in-place flowline assessment at the Cavey U 24-2J wellhead, historically impacted soil was discovered at the flowline sample FL07. The volume of the release is unknown. Assessment activities are ongoing. Portions of the flowline have been permanently removed and the status of the remaining flowline has been changed to out-of service.	maclarej	04/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300938	PA well location; no FL risers (view East)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522633
717300939	PA well location; no FL risers (view West)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522634