

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2026

Submitted Date:

04/21/2026

Document Number:

708908986

**FIELD INSPECTION FORM**

Loc ID 481743 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: 402609520

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 45 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	
Metz, Collin		collin.metz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482542	WELL	PR	10/19/2025	GW	045-24518	CC Federal 0697-15-17W	PR
482543	WELL	PR	10/19/2025	GW	045-24519	CC Federal 0697-15-19W	PR
482544	WELL	PR	09/23/2025	GW	045-24520	CC 0697-10-15E	PR
482545	WELL	PR	10/13/2025	GW	045-24521	CC 0697-15-19E	PR
482546	WELL	PR	10/17/2025	GW	045-24522	CC 0697-15-12E	PR
482547	WELL	PR	09/22/2025	GW	045-24523	CC 0697-15-13E	PR
482548	WELL	PR	09/23/2025	GW	045-24524	CC 0697-10-16E	PR
482549	WELL	PR	09/22/2025	GW	045-24525	CC 0697-15-02E	PR
482550	WELL	PR	09/22/2025	GW	045-24526	CC 0697-15-15E	PR
482551	WELL	PR	09/22/2025	GW	045-24527	CC 0697-15-14E	PR
482552	WELL	PR	09/23/2025	GW	045-24528	CC 0697-15-01E	PR
482553	WELL	PR	10/17/2025	GW	045-24529	CC 0697-10-12E	PR
482554	WELL	PR	10/17/2025	GW	045-24530	CC 0697-10-13E	PR
482555	WELL	PR	10/13/2025	GW	045-24531	CC 0697-15-18E	PR
482556	WELL	PR	10/19/2025	GW	045-24532	CC Federal 0697-15-18W	PR
482557	WELL	PR	09/01/2025	GW	045-24533	CC 0697-15-03E	PR
482558	WELL	PR	10/19/2025	GW	045-24534	CC 0697-10-11E	PR

482593	WELL	PR	09/23/2025	GW	045-24535	CC 0697-10-14E	PR
--------	------	----	------------	----	-----------	----------------	----

**General Comment:**

This is a Field Inspection/Audit of the scout card, related documents and the location.

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
	Type OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:			Date:

Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 18		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Plunger Lift	# 18		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 18		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 18		
Comment:	Pressure transducers located on bradenheads		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric motor & charge pump in tank battery secondary containment		
Corrective Action:		Date:	
Type: Other	# 9		
Comment:	Please refer to FORM 2A document # 402609520  Capstone generators, Qnergy air compressor, chemical tanks, pig station & electric motor with charge pump not listed in the above referenced document/not in compliance with CECMC Rules - Compliance issue previously referred to Location Assessment Group.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Qnergy air compressor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Capstone generators	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	Gunbarrel Tanks Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: <span style="color:blue;">Centralized containment</span>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	482542	Type:	WELL	API Number:	045-24518	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482543	Type:	WELL	API Number:	045-24519	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482544	Type:	WELL	API Number:	045-24520	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482545	Type:	WELL	API Number:	045-24521	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482546	Type:	WELL	API Number:	045-24522	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482547	Type:	WELL	API Number:	045-24523	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482548	Type:	WELL	API Number:	045-24524	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					
Facility ID:	482549	Type:	WELL	API Number:	045-24525	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

Facility ID: 482550	Type: WELL	API Number: 045-24526	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482551	Type: WELL	API Number: 045-24527	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482552	Type: WELL	API Number: 045-24528	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482553	Type: WELL	API Number: 045-24529	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482554	Type: WELL	API Number: 045-24530	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482555	Type: WELL	API Number: 045-24531	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482556	Type: WELL	API Number: 045-24532	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: 482557	Type: WELL	API Number: 045-24533	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		

Facility ID: 482558 Type: WELL API Number: 045-24534 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Facility ID: 482593 Type: WELL API Number: 045-24535 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Drill Cuttings		Inadequate	
Comment	Apparent cuttings/E & P waste migration onto & across location/not in compliance with CECMC Rules  Additionally there are multiple areas of staining on location		
Corrective Action	Contact ECMC Area EPS Staff Collin Metz & Alex Fischer		Date: 04/28/2026

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Sediment Traps						
		Culverts				
Drains						
		Ditches				
		Drains				
		Gravel				Sparse to none
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				Light compaction in some areas
Compaction						Light compaction in some areas
		Berms				
Gravel						Sparse to none in most areas
		Rip Rap				
Waddles						
		Sediment Traps				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 04/21/2026 at approximately 11:37 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad                      Location # 481743 in Garfield County Colorado.                      Please refer to inspection/audit 708908856 conducted on 03/31/2026, previous corrective action has been completed.                      Location is within Black Bear Habitat area &amp; in close proximity to High Priority Habitat area &amp; Greater Sage Grouse General Habitat Management Area.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Environmental/Waste Management - Apparent cuttings/E &amp; P waste migration onto &amp; across location/not in compliance with CECMC Rules with a CA date of 04/28/2026</p> <p>Comments -</p> <p>Equipment - Multiple pieces of equipment on location not listed in operators FORM 2A or FORM 4 SUNDRY - Previously referred to Location Assessment Group.</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	04/21/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908988	Inspection/Audit 708908986 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522675">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522675</a>