

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #49AX

Location ID: 316504

Date: 04/8/2026



Photo # 4251 Entrance to location



Photo # 4353 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #49AX

Location ID: 316504

Date: 04/8/2026



Photo # 4354 Wellhead sign lacks public road used to access the well

Photo # 4363 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #49AX

Location ID: 316504

Date: 04/8/2026



Photo # 4365 Location

Photo # 4366 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #49AX

Location ID: 316504

Date: 04/8/2026



Photo # 4368 Debris



Photo # 4370 Debris