

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/15/2026

Document Number:

701104681

**FIELD INSPECTION FORM**

Loc ID 426123 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426125	WELL	PR	01/31/2013	GW	045-21126	Bosely SG 542-23	EG
426128	WELL	PR	02/13/2013	GW	045-21127	Bosely SG 442-23	EG
426132	WELL	PR	01/28/2013	GW	045-21128	Bosely SG 33-23	EG
426133	WELL	PR	01/28/2013	GW	045-21129	Bosely SG 42-23	EG
426141	WELL	PR	02/13/2013	GW	045-21130	Bosely SG 342-23	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Hole tank battery liner.  
Repair hole in liner and inspect liner for integrity.  
CA Date 4/25/2026  
Chem tank secondary containment full of fluid.  
Remove fluid to allow for spills.  
CA Date 4/25/2026  
No plug in bottom valves of glycol vesseles of separators.  
Install plugs in valves to prevent spill.  
CA Date 4/25/2026

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 5		
Comment: <span style="color: blue;">No plug in bottom valves of glycol vesseles of separators.</span>			
Corrective Action: <span style="color: red;">Install plugs in valves to prevent spill.</span>			Date: <u>04/25/2026</u>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	<input style="width: 100%;" type="text"/>

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:	Some bottom valves are rusted and corroded.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Hole tank battery liner.			
Corrective Action:	Repair hole in liner and inspect liner for integrity.			Date: 04/25/2026

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 426125 Type: WELL API Number: 045-21126 Status: PR Insp. Status: EG

Facility ID: 426128 Type: WELL API Number: 045-21127 Status: PR Insp. Status: EG

Facility ID: 426132 Type: WELL API Number: 045-21128 Status: PR Insp. Status: EG

Facility ID: 426133 Type: WELL API Number: 045-21129 Status: PR Insp. Status: EG

Facility ID: 426141 Type: WELL API Number: 045-21130 Status: PR Insp. Status: EG

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Chem tank secondary containment full of fluid.

Comment: Chem tank secondary containment full of fluid.

Corrective Action: Remove fluid to allow for spills.

Date: 04/25/2026

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404621212	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515450">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515450</a>
701104682	Flowline integrity inspection 701104681 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515449">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515449</a>