

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/15/2026

Document Number:

713401358

FIELD INSPECTION FORM

Loc ID 315729 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Saint, John		jsaint@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	
Beasley, Nolan		nolan.beasley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231463	WELL	IJ	06/27/2025	ERIW	103-09133	FEE 141X	AC

General Comment:

[Routine UIC inspection. Active injection at time of inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks public road used to access the well. No tank battery on location		
Corrective Action:	Comply with CECMC rule 605		Date: 05/15/2026

Emergency Contact Number:			
Comment:	970-675-3700		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location, refer to photos		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	WAG skid		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 231463 Type: WELL API Number: 103-09133 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1610 Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: WEBR
TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 08/08/2022
Brhd: Pressure or inches of Hg 165 Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection.

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 220 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				Light compaction
		Ditches				
		Culverts				
Compaction						Light compaction

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 04/6/2026 at approximately 11:07 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC FEE #141X at Location ID #315729 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal UIC operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Wellhead sign lacks public road used to access the well with a CA date of 05/15/2026</p> <p>Comments -</p> <p>1. Housekeeping - Debris on location.</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	04/15/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404620664	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515088
713401359	713401358 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515084