

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/15/2026

Document Number:

713401362

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
315530 \_\_\_\_\_ Popejoy, Dusty \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10779  
Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
Address: 13800 MONTFORT DRIVE SUITE 100  
City: DALLAS State: TX Zip: 75240

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                     | Comment |
|----------------|-------|---------------------------|---------|
| Wiley, Mikel   |       | Mikel.Wiley@scoutep.com   |         |
| Beasley, Nolan |       | nolan.beasley@state.co.us |         |
| Sanford, Anita |       | anita.sanford@scoutep.com |         |
| Rosado, Sydney |       | Sydney.Rosado@scoutep.com |         |
| Saint, John    |       | jsaint@scoutep.com        |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 230994      | WELL | IJ     | 06/26/2019  | ERIW       | 103-08663 | FEE 122X      | AC          |

**General Comment:**

[Routine UIC inspection. Active injection at time of inspection.](#)

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           | Access |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |  |  |                  |
|----------------------|--|--|------------------|
| <b>Signs/Marker:</b> |  |  |                  |
| Type                 | OTHER  |  |                  |
| Comment:             | Sign at entrance to location   |  |                  |
| Corrective Action:   |  |  | Date:            |
| Type                 | WELLHEAD   |  |                  |
| Comment:             | Wellhead sign lacks public road used to access the well. No tank battery on location |  |                  |
| Corrective Action:   | Comply with CECMC rule 605   |  | Date: 05/15/2026 |

|                                  |                  |  |             |
|----------------------------------|------------------|--|-------------|
| <b>Emergency Contact Number:</b> |                  |  |             |
| Comment:                         | 970-675-3700/911 |  |             |
| Corrective Action:               |                  |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                           |  |  |                 |
|---------------------------|--|--|-----------------|
| <b>Equipment:</b>         |  |  | corrective date |
| Type: Deadman # & Marked  | # 4  |  |                 |
| Comment:                  |  |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Bradenhead          | # 1  |  |                 |
| Comment:                  | Bradenhead valve is accessible/equipped with gauge |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Ancillary equipment | # 1  |  |                 |
| Comment:                  | WAG skid   |  |                 |
| Corrective Action:        |  |  | Date:           |

|                    |    |  |       |
|--------------------|----|--|-------|
| <b>Venting:</b>    |    |  |       |
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |
| Comment:        |  |  |  |

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 230994 Type: WELL API Number: 103-08663 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg 1485 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: WEBR  
TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 06/29/2022  
Brhd: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC inspection. Active injection at time of inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment          |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------|
|                  |                 | Ditches                 |                       |               |                          |                  |
| Berms            |                 |                         |                       |               |                          |                  |
| Compaction       |                 |                         |                       |               |                          | Light compaction |
|                  |                 | Compaction              |                       |               |                          | Light compaction |
| Ditches          |                 |                         |                       |               |                          |                  |

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 04/6/2026 at approximately 13:21 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC FEE #122X at Location ID #315530 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal UIC operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Wellhead sign lacks public road used to access the well with a CA date of 05/15/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p> | popejoyd | 04/15/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 404620669    | INSPECTION SUBMITTED              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515090</a> |
| 713401363    | 713401362 Inspection-Audit Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515086">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515086</a> |