

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2026

Submitted Date:

04/15/2026

Document Number:

719700633

FIELD INSPECTION FORM

Loc ID 322722 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244141	WELL	TA	03/02/2026	OW	123-11934	OWL CREEK 13	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	OOSLAT applied at well, separator(s). *Refer to Emergency Contact Number section below.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Emergency contact number NOT posted at wellsite. Refer to Rule 605.d for guidance.		
Corrective Action:	*Post emergency contact number at wellsite. Comply with Rule 605.d. (30-days). 05/15/2026. See photo(s) #1.		Date: 05/15/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.550918,-104.582544

Comment:	Centralized Battery serves 1 Location ID (322722). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 244141 Type: WELL API Number: 123-11934 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator(s).
ECMC records last prod: 02/2024.

Form 5A on file. TA date: 02/25/2026.
DH-CIBP.
Form 21-MIT on file. MIT date: 02/26/2026.
CIBP remains DH post MIT.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/03/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (322722). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700633 and/or Location ID #322722 for TA Well(s) info. B.) Field Audit Report doc. #719700635 and/or Location ID #322722 for Battery / Facility, Equipment info.</p>	evinsb	04/15/2026
<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On MON 04/13/2026 at approximately 16:18 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Location Name: OWL CREEK-67N64W/29NWNW Location ID: 322722 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTION ITEM(s): 2 1.) Refer to pg 2, "Signs/Marker" section of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	04/15/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404621739	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515999
719700634	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515993