

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2026

Submitted Date:

04/23/2026

Document Number:

721100351

FIELD INSPECTION FORM

Loc ID 313604 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286980	WELL	TA	06/01/2025	CO2	083-06627	YB 5	TA

General Comment:

On Wednesday, April 22, 2026 at 15:00 hours, southwest compliance specialist Jamie Blair performed a compliance inspection and audit. No corrective actions were identified. Photos are included as a link in the attachments section of this report.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Near entrance gate by pad, not lower locked gate. Photo 1.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4 strand barbed wire.

Corrective Action: _____ Date: _____

Equipment:

corrective date

Type: Other	# 1				
Comment:	Wellhead. Flowline removed.				
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	accessible.				
Corrective Action:		Date:			
Type: Flow Line	# 2				
Comment:	Flow line riser with OOSLAT tag marked out of service and flow line valve riser.				
Corrective Action:		Date:			

Venting:

Yes/No NO

Comment:

Corrective Action: _____ Date: _____

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286980 Type: WELL API Number: 083-06627 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Flow line segment removed. Riser is marked.
MIT Date 05/28/2025.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 07/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					NE corner.
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: No erosion or evidence of sediment transported off location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100352	Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7524254