

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



Wellhead Fencing/Debris – Photo #03519



Unused Gas Meter – Photo #03513

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



Unused Gas Meter – Photo #03515



Unused Storage Tank – Photo #03527

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



Unused Storage Tank – Photo #03528



Pit – Photo #03526

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



P&A Cutoff Plate – Photo #03522



Flowline Excavation – Photo #03521

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



Open-Ended Flowline – Photo #03523



Debris – Photo #03518

## Audit Photos

Location Name: VISION ENERGY LLC, COYOTE WASH UNIT-68S102W/27NWSW

Location ID: 312521

Date: 4/13/2026



Wildlife Entry Hazards – Photo #03529



Wildlife Entry Hazard – Photo #03530