

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2026

Submitted Date:

04/17/2026

Document Number:

701104692

**FIELD INSPECTION FORM**

Loc ID: 334889 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259288	WELL	PR	11/01/2022	GW	045-07704	BENZEL 35-8	EG
259289	WELL	PR	11/01/2022	GW	045-07706	DEVER 36-12 (H35)	EG
259290	WELL	PR	11/01/2022	GW	045-07705	DEVER 36-5 (H35)	EG
259291	WELL	PR	11/01/2022	GW	045-07707	BENZEL 35-9 (H35)	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Follow up to 2/25/2026 inspection 701104542  
Corrective action has not made.  
Production tank top is rusted out.  
Comply with Rules 608.a.(10) Tank Venting Standards and 608.e Mechanical Conditions.  
CA Date 3/17/2026

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment: Production tank top is rusted out.					
Corrective Action: : Comply with Rules 608.a.(10)Tank Venting Standards and 608.e Mechanical Conditions.					Date: 03/17/2026

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: <u>259288</u>	Type: <u>WELL</u>	API Number: <u>045-07704</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259289</u>	Type: <u>WELL</u>	API Number: <u>045-07706</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259290</u>	Type: <u>WELL</u>	API Number: <u>045-07705</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259291</u>	Type: <u>WELL</u>	API Number: <u>045-07707</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404625302	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7519022">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7519022</a>
701104693	Flowline integrity inspection 701104692 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7519018">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7519018</a>