

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2026

Submitted Date:

04/20/2026

Document Number:

715802223

FIELD INSPECTION FORM

Loc ID 318263 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241002	WELL	PR	03/01/2025	GW	123-08790	VERA L MCCANNON 2	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	the sign is faded & needs to be updated.		
Corrective Action:	Install sign or correct sign per rule 605	Date:	04/28/2026

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around the wellhead riser & by the gas engine		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	05/05/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date: _____
Type	WELLHEAD		
Comment:	wood & metal post with barb wire		
Corrective Action:			Date: _____

Equipment:

Type:	#			corrective date
Comment:	No change from previous FIR			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: _____

Flaring:

Type			
Comment:			
Corrective Action:			Date: _____

Inspected Facilities

Facility ID: 241002 Type: WELL API Number: 123-08790 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI valves are closed gas engine is not running

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/26/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 4-20-2026 at approximately 1545 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 318263 API # 05-123-08790 Well name: Vera L McCannon 2 County: Weld Weather: Partly Cloudy Temp: 82* Location: dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 608.e housekeeping: Stained soil by the wellhead riser & by the gas engine needs to be cleaned, CA date 5-5-26. 605 signs: sign is faded, CA date 4-28-2026 Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. I spoke with (Name & Title) (Company) what was discussed. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	04/20/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404627210	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520833
715802224	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520831