

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/20/2026

Document Number:

719201051

FIELD INSPECTION FORM

Loc ID 324132 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10271
 Name of Operator: WHITE RIVER DEVELOPMENT COMPANY LLC
 Address: 4692 N 300 WEST #209
 City: PROVO State: UT Zip: 84604

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Robert Hammond		robert@mwigroup.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258780	WELL	PA	10/29/2019	GW	045-07656	WOODWARD 1	RI
324132	LOCATION	CL			-	WOODWARD-64S94W 22SESW	RI

General Comment:

On 04/09/2026, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at White River Development Company LLC's WOODWARD-64S94W/22SESW location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:
 -Noxious weeds and undesirable plant species

Refer to the ECMC Comments section of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Inspected Facilities

Facility ID: 258780 Type: WELL API Number: 045-07656 Status: PA Insp. Status: RI

Facility ID: 324132 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% Pass Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% 40
 TRANSECT RESULTS OF REFERENCE AREA% 38
 TOTAL % OF DESIRABLE VEGETATION COVER 105
 VEGETATIVE COVER PASS

Comment:

Corrective Action:

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Reclamation Comments: This location meets 1004.a. final reclamation requirements of desirable, perennial and uniform vegetation of at least eighty (80) percent vegetative cover of a nearby reference area. Vegetation transects were performed on the disturbed and reference areas and found that vegetation on the reclaimed area is 105% of the nearby reference area, located directly west of the location in a mature big sagebrush stand.</p> <p>The location access road was not reclaimed per approved Surface Owner Final Reclamation Variance #1309807. However, bull thistle, a List B noxious weed, is well-established and dense on the road and weed control is required per Rule 1004.e. The road is populated with previous seasons' mature growth and basal rosettes, indicating that the infestation is spreading.</p> <p>The location itself is well-established with perennial grasses, such as western wheatgrass and other perennial grass species. Rubber rabbitbrush and big sagebrush are present in secondary to tertiary amounts. Bull thistle basal rosettes were scattered throughout, but mature perennial vegetation appears to be competing with undesirable thistle. Bull thistle has established in dense amounts on the southern portion of the location where the site meets the access road. Young basal rosettes of other undesirable plant species, identified as either common mullein or houndstongue (which has been observed at this location in the past) were observed in secondary to tertiary amounts throughout the location.</p> <p>ECMC requires that bull thistle basal rosettes and other undesirable plant species are treated/controlled along the access road and at the location during the 2026 growing season before it receives a passing final reclamation inspection. Inspector can be reached at 720-765-3961 to further discuss details at this location.</p> <p>See Corrective Action under Reclamation section of report. See vegetation transect data sheet attached. See photo attachment for more details.</p>	gaaschee	04/20/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404627055	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520622
719201052	Vegetation Transect Data Sheet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520613
719201053	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520614