

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2026

Submitted Date:

04/27/2026

Document Number:

707801971

FIELD INSPECTION FORM

Loc ID 414020 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95960
Name of Operator: WEXPRO COMPANY
Address: P O BOX 45003
City: SALT LAKE CITY State: UT Zip: 84145-

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Polk, Josette		josette.polk@enbridge.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
411959	WELL	PR	06/01/2023	GW	081-07468	B W MUSSER 31	PR
418298	WELL	SI	01/01/2025	GW	081-07617	Carl Allen Unit 37	PA
418299	WELL	PR	06/01/2023	GW	081-07618	BW MUSSER 38	PR
418306	WELL	PR	06/01/2023	GW	081-07619	B.W. MUSSER 39	PR

General Comment:

[ECMC Inspection Report Summary](#)
On Wednesday 4/1/2026, I, Inspector Scott Ramsey, conducted a routine inspection/audit on site at Wexpro Musser BWB 31, at Location # 414020 in Moffett County Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, NSO habitat, Wildlife Density habitat.
During this inspection the following possible compliance issues were observed:
1. Battery signage lacks information
2. Well signage lacks information
3. Random debris
4. Stored equipment
5. Some staining

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well signage lacks information		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery signage lacks information		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	800-341-3129/911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Random staining inside containment and around well heads		
Corrective Action:	Remove and dispose of contaminated material properly		Date: 05/29/2026
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris		Date: 05/08/2026
Type	STORAGE OF SUPL		
Comment:	Stored equipment		
Corrective Action:	Remove, put into service or provide proper documentation for stored equipment		Date: 05/08/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks in containments		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Running and not metered		
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 411959 Type: WELL API Number: 081-07468 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>Producing</u>	
Corrective Action:		Date:

Facility ID: 418298 Type: WELL API Number: 081-07617 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was recently plugged and abandoned. For 6 on file and approved document # 404512788

Corrective Action:		Date:
--------------------	--	-------

Facility ID: 418299 Type: WELL API Number: 081-07618 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>Producing</u>	
Corrective Action:		Date:

Facility ID: 418306 Type: WELL API Number: 081-07619 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>Producing</u>	
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801975	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528113