

The excavation at the spill location remains open. Weeds obscure visibility of the majority of the excavation base and sidewalls. Barbed wire fencing surrounds the excavation.



Frederick, CO, United States
Lat 40.123489, Long -105.013423
03/25/2026 14:45 GMT-06:00
ECMC : Environmental Inspection

11.07 mph 4894.26 ft 4.75 m

86°F 335° NW

Salt crusting is visible within the excavation.



Frederick, CO, United States
Lat 40.123462, Long -105.013302
03/25/2026 14:45 GMT-06:00
ECMC : Environmental Inspection

11.07 mph 4893.7 ft 4.75 m

86°F
296° NW

A network of monitoring wells completed as PVC stickups was observed on location.



Frederick, CO, United States
Lat 40.123442, Long -105.013346
03/25/2026 14:45 GMT-06:00
ECMC - Environmental Inspection

11.07 mph 4902.62 ft 4.62 m

86°F 121° SE

DRR