

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2026

Submitted Date:

04/28/2026

Document Number:

719201067

FIELD INSPECTION FORM

Loc ID 398469 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231989	WELL	PA	01/14/2003	GW	103-09660	BMU 2511	RI
398469	LOCATION	CL			-	BMU-61N95W 26NWNW	RI

General Comment:

On 04/16/2026, NW Reclamation Specialist Emily Gaasche conducted a follow-up final reclamation inspection at QB Energy/Caerus Piceance LLC's BMU 2511 Location in Rio Blanco County, Colorado.

Location is within the following CPW High Priority Habitat: within 1/4 mile of a Bald Eagle Active Nest Site, Bald Eagle /12 Mile Active Nest Site and Aquatic Sportfish Management Waters

No new compliance issues were observed during this inspection. However, the location does not meet 1004 vegetation uniformity requirements.

Refer to the ECMC Comments section of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Inspected Facilities

Facility ID: 231989 Type: WELL API Number: 103-09660 Status: PA Insp. Status: RI

Facility ID: 398469 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded Pass Contoured _____ Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage In

Weeds present Pass Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Reclamation Comments: Previous inspection #719200084 observed that the location lies within an irrigated perennial cropland composed of mixed pasture grasses. ECMC Reclamation Specialist discussed the Location with the Surface Owner, who indicated their dissatisfaction with the reclamation work performed, and that the Location has not been properly contoured for successful irrigation throughout the disturbance area. Canada thistle, a List B noxious weed, had established throughout the location.</p> <p>Previous inspection #719200084 required additional 1004 efforts; Operator was required to collaborate with the surface owner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production. Consultation documentation and Reclamation Schedule attached to a Form 4 Sundry Notice and submitted to the Area Reclamation Specialist for review by 10/22/2025 was required; however, no Form 4 has been received by Reclamation Specialist. FIRR # 404472447 states "Maintenance completed to ensure compliance with Rule 1004." Details of maintenance efforts are unknown.</p> <p>This inspection observed that Canada thistle throughout the location has been treated (per FIRR #404420912), and no new thistle rosettes were observed. This Corrective Action has been resolved. Ongoing weed maintenance and monitoring is required until the location receives a passing final reclamation inspection.</p> <p>This inspection observed that the location appears predominantly bare in portions of the location, and vegetation is not uniform. Compaction issues may persist. Vegetation at the location does not meet 1004 uniformity standards. A follow-up inspection will be conducted during future growing seasons to determine compliance with 1004 reclamation requirements.</p>	gaaschee	04/28/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719201068	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528841