

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2026

Submitted Date:

04/28/2026

Document Number:

719501070

**FIELD INSPECTION FORM**

Loc ID 312578 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10770  
Name of Operator: VISION ENERGY LLC  
Address: P O BOX 370  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 13 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wang, Jian		jian.wang@state.co.us	
Energy, Vision		mollieo@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221954	WELL	SI	01/01/1984	GW	077-08556	CAMP GULCH UNIT-FEDERAL 3-22-8-103	SI

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 4/21/2026 at approximately 14:35, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/22NESE at Location ID #312578 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Storage tank on location is unused equipment.		
Corrective Action:	Remove unused equipment from location.	Date:	05/29/2026
Type	WEEDS		
Comment:	Weeds are present across location.		
Corrective Action:	Remove weeds from location.	Date:	05/06/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:	Livestock fencing		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter house is unsecured and poses a wildlife entry hazard.		
Corrective Action:	Comply with CECMC wildlife safety rules.	Date:	05/04/2026

Type: Dehydrator	# 1		
Comment:	Dehydrator is unsecured and poses a wildlife entry hazard.		
Corrective Action:	Comply with CECMC wildlife safety rules.		Date: 05/04/2026
Type: Horizontal Heated Separator	# 1		
Comment:	Wildlife entry hazard on separator.		
Corrective Action:	Comply with CECMC wildlife safety rules.		Date: 05/04/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<100 BBLS	Open Top		
Comment:	Storage tank is corroded in multiple areas and open to wildlife.				
Corrective Action:	Comply with CECMC wildlife safety rules.			Date:	05/04/2026

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment is installed at storage tank. Tank is disconnected, empty, and is unused equipment. Refer to Housekeeping Corrective Action.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 221954 Type: WELL API Number: 077-08556 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last produced January 2004. Last MIT performed 6/26/2012. Well is overdue for MIT.

Corrective Action: Comply with CECMC Mechanical Integrity Testing requirements. Date: 10/11/2024

**BradenHead**

Date of Last Brhd Test: 10/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last Bradenhead test performed 4/9/2026.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <ul style="list-style-type: none"> <li>1) Weeds are present across location</li> <li>2) Unused storage tank on location</li> <li>3) Wildlife entry hazards at gas meter house, dehydrator, separator, and storage tank</li> <li>4) Well is overdue for Mechanical Integrity Testing</li> </ul> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	04/28/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719501071	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529990">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529990</a>