

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>04/22/2026</u> Submitted Date: <u>04/22/2026</u> Document Number: <u>719001794</u>
FIELD INSPECTION FORM			

Loc ID 333116 Inspector Name: GARCIA, CHARLES On-Site Inspection
 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
McDonough, Corey		corey.mcdonough@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213801	WELL	PR	02/01/2022	CBM	067-05064	ABEYTA 17-1	PR
295624	WELL	PR	09/13/2008	CBM	067-09535	ABEYTA 17-2	PR

General Comment:

[Inspection Report Summary](#)
 On 4/22/26 | Inspector Charles Garcia conducted an on-site inspection.
 Location: ABEYTA 17-1, ABEYTA 17-2
 API# 067-05064
 API# 067-09535
 Operator: HILLCORP ENERGY COMPANY
 County: LaPlata
 All prior CA's still stand

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		Date:
Corrective Action:			
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	LANDOWNER HAS A PIPE TRAILER PICKUP TRUCK AND PLOW STORED ON LOCATION		
Corrective Action:	Store equipment off pad/interim reclamation area or obtain variance per rule 606.a(2)		Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	SOUND WALLS		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment			# 2
Comment:			TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION
Corrective Action:			Date:
Type: Gas Meter Run			# 2
Comment:			
Corrective Action:			Date:
Type: Flow Line			# 2
Comment:			
Corrective Action:			Date:
Type: Prime Mover			# 1
Comment:			GAS
Corrective Action:			Date:

Corrective Action:		Date:	
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	MARKERS ARE ON GROUND		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 213801 Type: WELL API Number: 067-05064 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 295624 Type: WELL API Number: 067-09535 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
LANDOWNER HAS A PIPE TRAILER PICKUP TRUCK AND PLOW STORED ON LOCATION Store equipment off pad/interim reclamation area or obtain variance per rule 606.a(2)	garciacr1	04/22/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404630982	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7524150
719001795	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7524147