

## Inspection Photos

Operator: **AMERICAN HELIUM OPERATING LLC - 10841**

Location Name: **STATE 1-36H**

Location ID: **333120**

API #: **05-113-06047**

Inspection Date: **4/23/2026** Inspection Doc#: **693809241**



**Location overview looking S**



**Wellhead with fence and sign**

## Inspection Photos

Operator: **AMERICAN HELIUM OPERATING LLC - 10841**

Location Name: **STATE 1-36H**

Location ID: **333120**

API #: **05-113-06047**

Inspection Date: **4/23/2026** Inspection Doc#: **693809241**



**Separator and Meter housing  
Disconnected and blind flanged**



**Open ended flowline at meter housing**

# Inspection Photos

Operator: **AMERICAN HELIUM OPERATING LLC - 10841**

Location Name: **STATE 1-36H**

Location ID: **333120**

API #: **05-113-06047**

Inspection Date: **4/23/2026**

Inspection Doc#: **693809241**



**Open ended flowline at separator**



**Off location flowline**

# Inspection Photos

Operator: **AMERICAN HELIUM OPERATING LLC - 10841**

Location Name: **STATE 1-36H**

Location ID: **333120**

API #: **05-113-06047**

Inspection Date: **4/23/2026**

Inspection Doc#: **693809241**



**Tank Battery**



**Tank with rust holes**