

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



1. Well sign.

2. Pump jack and wellhead. Note mineral crust near base

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658




3. Wellhead, pump jack and prime mover (behind cattle panel fence).

4. Wellhead. Mineral crust building up, but no active leaks observed.

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



5. Close up of wellhead. Valve handle removed below pen.



6. Flow line, meter run and solar telemetry. Meter calibration inside box.

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



7. Prime mover. Appears to be in working condition but not operating during inspection.



8. Lube oil container for prime mover above spill prevention.

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



9. Meter run. Label says calibration card is inside box. Not prominently displayed.

10. Interim reclamation vegetation. Rig anchor marker is down.

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



11. Rig anchor marker in NE corner looking west.

12. Reclamation vegetation on east edge looking south.

Inspection Photos

Location Name: Enduring Resources Indian Creek Wheeler 12U-4

Location ID: API 05-067-08658



13. Access gate at bottom of access road.

14. Access road from well pad.