

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2026

Submitted Date:

04/29/2026

Document Number:

721100369

FIELD INSPECTION FORM

Loc ID 326666 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blair, Jamie		jamie.blair@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261762	WELL	PR	11/01/2020	CBM	067-08658	WHEELER 12U-4	PR

General Comment:

On Tuesday, April 28, 2026 at 16:20 hours, southwest compliance specialist Jamie Blair performed a compliance inspection and audit. Photographs are linked in the attachment section. One corrective action was identified.

Location			
Lease Road:			
Type	Access		
comment:	Steep cut and fill but with solid rock base.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Near meter run by entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1(800) 916-7897 or 911,		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Note: Some mineral crust from evaporated produced water beneath wellhead. Approx 6 sq. ft. Photo 4.		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Down pin-flags observed in several locations on pad. Photo 3.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	cattle panel		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 0		
Comment:	removed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	well gas power.		

Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Underground from wellhead to meter run. Above ground by meter run.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	solar telemetry		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Note - SE corner rig anchor marker is down. Other 3 are standing. See photon 10.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	accessible		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration card is inside meter run box. Not conspicuously displayed. Photo 9.		
Corrective Action:	Conspicuously display meter run card to comply with 430.d.(2)		Date: 05/12/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 261762 Type: WELL API Number: 067-08658 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/28/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: accessible.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [No erosion observed or sediment migration off site. Hard rock in area.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100371	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7531630