

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/29/2026

Document Number:

708909051

**FIELD INSPECTION FORM**

Loc ID 324452 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: 2094319

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
TEP		ECMCInspectionReports@flywheelenergy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300179	WELL	PR	08/16/2011	GW	045-17847	SAVAGE PA 522-9	PR

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 300179 Type: WELL API Number: 045-17847 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	Date: <u>04/16/2026</u>

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 04/29/2026 at approximately 18:10 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9                      Location # 324452 in Garfield County Colorado.                      Please refer to inspection/audit 708908723 conducted on 03/17/2026, 1 of 2 previous corrective actions has been completed.                      Location is within High Priority/Density/Black Bear Habitat areas.                      Location is within Rule 411a Surface Water External Buffer.                      Location is approximately 40 yards from Rule 411b Generalized External Buffer.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - SAVAGE PA 522-9 lacks wellbore diagram - Comply with Rule 420 with a CA date of 04/16/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of desktop inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	04/29/2026