

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2026

Submitted Date:

04/30/2026

Document Number:

720800437

FIELD INSPECTION FORM

Loc ID: 405138 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 92950
Name of Operator: VAUGHEY & VAUGHEY
Address: 1840 CAPITOL TOWERS
City: JACKSON State: MS Zip: 39201-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|--------------------------|---------|
| SAADEH, RICHARD | | richard.saadeh@mdsed.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 238605 | WELL | PA | 07/03/1969 | ERIW | 123-05468 | BUCKINGHAM TOWNSITE UNIT 1 | PA |

General Comment:

[This is a Re-Entry and Re-Plug and Abandon Field Audit of the Scout Card, Related Documents and the Location](#)

Inspected Facilities

Facility ID: 238605 Type: WELL API Number: 123-05468 Status: PA Insp. Status: PA

Workover

Comment: Drilling - TD @ 1172'; lost circulation, lines plugged up, Crew will clear lines in AM

Corrective Action:

Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 720800438 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533065 |