


## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



1. Well Sign by pad entrance and separator. Operator name is peeling off and is not legible. Phone number confirmed to be Enduring 24 Hour contact.

2. Wellhead and pumpjack. Horsehead is removed from walking beam. Polished rod not present or in hole.

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**3. Location overview from pad entrance near well sign.**

**4. Location overview from interim reclamation area.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



5. Wellhead.



6. Side view of pump jack with horsehead removed and lying on ground.

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**7. Side view of pumpjack and wellhead.**



**08. Prime mover. Motor appears to have electrical and fuel supply disconnected.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



9. Pumpjack labelled out of service by prime mover.



10. Pumpjack labelled out of service near wellhead.

# Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



11. Vertical heated separator/meter run combination. Meter calibration card displayed inside door on right side inside plastic sleeve. Dated 07/07/2023. Labelled “Chevron Midstream” not “Enduring Resources”.

12. Produced water tank. Labelled “Chevron Midcontinent” not “Enduring Resources”. Other required info present.


## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**13. Open topped steel produced water tank from SE Corner. Lat Long = 37.201296/-107.863501. Berm appears to be adequate.**



**14. Various pipe segments on ground between separator and tank.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**15. Tank behind cattle panel fence and heated separator/meter run structure. Bird protector on heater stack. Solar telemetry.**



**16. Ditch on road approaching pad. Alternating cobble check dams and straw wattles. All appear to be full of sediment and water is flowing around causing erosion.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**17. Overview of well pad from SE corner looking NW. Rig anchor marker is down. Also marked with "Gas Pipeline" fiberglass marker.**

**18. Diversion berm on southern reclamation area cut slope.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**19. Straw wattles in southern reclamation area run-on diversion ditch are full of sediment.**

**20. Straw wattles in run-on diversion ditch are full of sediment.**

## Inspection Photos

Location Name: Endruing Resources Indian Creek Wheeler #12-U

Location ID: API 05-067-07636



**21. Interim reclamation and drainage ditch on east end of well pad.**

**22. Down rig anchor marker in SW corner.**