

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



1. Well sign.



2. Wellhead, and pumpjack.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647




3. Wellhead and pumpjack. There was produced water leaking from the stuffing box at the beginning of the inspection. The operator was contacted and a pumper showed up, tightened and greased the fitting, and stopped the leak during the inspection. There is a damp spot beneath the wellhead that resulted from the leak, but no standing water.

4. Pumpjack, wellhead and electric prime mover.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



5. Wellhead and pumpjack. Cattle panel fence surrounds pump jack.

6. Wellhead. 4'x8' estimated damp spot caused by leak observed during inspection. Operator was contacted about leak, which was fixed, but affected material remains.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



9. 2-inch flow line riser, possibly from when tank and separator were still on location.

10. Rig marker anchors on south end.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



11. Rig anchor markers on north end.

12. Gravel and riprap armored drain through berm on south end of pad is beginning to erode.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



13. Riprap- armored drain and sediment retention feature is functional, but is filling with sediment.



14. Location access road and south end of pad looking west.

Inspection Photos

Location Name: Enduring Resources - Indian Creek Wheeler 13-4

Location ID: 05-067-08647



15. Location overview looking northwest from southeast corner.