

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

710500779

**FIELD INSPECTION FORM**

Loc ID 439367 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
4 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 10412  
 Name of Operator: AUSCO PETROLEUM INC  
 Address: 113 N SANTA FE AVENUE  
 City: FLORENCE State: CO Zip: 81226

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	<a href="#">All Inspections</a>
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	<a href="#">All Inspections</a>
Waggoner, Kyle		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	PA	07/31/2025	OW	043-06227	Columbus 1	EI

**General Comment:**  
 This is a follow up Environmental Inspection for the Columbus 1 well location located in Fremont County, Colorado  
 API # 05-043-06227  
 Location ID 439367  
 Pathfinder C-18 8  
 Remediation Project # 41043  
 Inspection # 710500676  
 Inspection # 710500727

**Inspected Facilities**

Facility ID: 439366 Type: WELL API Number: 043-06227 Status: PA Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: This is a follow up Environmental Inspection for Remediation Project # 41043.  
 At the time of inspection, the wellhead excavation was backfilled.  
 Operator has not provided analytical data for Remediation Project # 41043 to confirm the presence or absence of impact to soils within the wellhead excavation.  
 Initial Form 27-I was submitted on 06/18/2025 and approved on 06/30/2025. The approved reporting schedule was identified as 90 days after receipt of analytical. Form 6-S document no. 404300603 indicates the well was cut and capped on 7/31/2025.  
 Operator shall submit a Supplemental Form 27-S in accordance with the reporting schedule approved in Form 27-I document no. 404300603.

Corrective Action: Previously assigned corrective action date shall apply 01/30/2026 Date: 01/30/2026

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500780	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533798">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533798</a>