

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/30/2026

Document Number:

701104722

**FIELD INSPECTION FORM**

Loc ID 312668 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Safety sticker (DANGER) on separator unit is weathered and mostly gone.  
Comply with Rule 605.g.(2)  
CA Date: 06/30/2026  
Seep hole on side of tank.  
Tank has been sprayed black product.  
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA Date 05/15/2026  
After repairs are made paint production tank per Rule 425.b.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY	Date:	
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS	Date:	
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD	Date:	
Comment:			
Corrective Action:		Date:	
Type	OTHER	Date:	
Comment:	Safety sticker (DANGER) on separator unit is weathered and mostly gone.		
Corrective Action:	Comply with Rule 605.g.(2)	Date:	06/30/2026

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:	Seep hole on side of tank. Tank has been sprayed black product.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. After repairs are made paint production facilities per Rule 425.b.				Date: 05/15/2026

**Paint**

Condition: Inadequate

Other (Content):

Other (Capacity): 95 bbls

Other (Type):

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104723	Flowline integrity inspection 701104722 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533977</a>