

Inspection Photos

Location Name: Rainbow 23-20

API #: 05-043-06150

Location ID: 322234



Photo 1: Well Placard at gate entrance

Photo 2: Location Overview from access road

Inspection Photos
Location Name: Rainbow 23-20
API #: 05-043-06150
Location ID: 322234



Photo 3: Electrical Panels

Photo 4: Electrical trench looking to north to wellhead

Inspection Photos
Location Name: Rainbow 23-20
API #: 05-043-06150
Location ID: 322234



Photo 5: Guarding from excavations



Photo 6: Spoil Pile

Inspection Photos
Location Name: Rainbow 23-20
API #: 05-043-06150
Location ID: 322234



Photo 7: Excavation location backfilled

Photo 8: Excavation Location backfilled

Inspection Photos
Location Name: Rainbow 23-20
API #: 05-043-06150
Location ID: 322234



Photo 9: Excavation area backfilled

Photo 10: Excavation area backfilled

Inspection Photos
Location Name: Rainbow 23-20
API #: 05-043-06150
Location ID: 322234



Photo 11: Plugged culvert access road and location.

Photo 12: Erosion along access road.