

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 1 – Well Placard

Photo 2 – Location Overview

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 3 – Electrical Equipment

Photo 4 – Electrical Line corridor

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 5 – Impacted spoil pile in containment

Photo 6 – Former Tank Battery/area with impacts to soils

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 7 – Former Wellhead location

Photo 8 – Open Excavation

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 9 – Open Excavation

Photo 10 – Open Excavation

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 11 – Disturbance behind excavation

Photo 12 – Open Excavation

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 13 – Open Excavation

Photo 14 – Rilling along cut slope

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



Photo 15 – Erosion on cut slope

Photo 16 – Stormwater BMP at the top of cut slope is full, breach in dyke at red arrow

Inspection Photos
Location: Rainbow 23-20
Location ID: 322234
API # 05-043-06150



**Photo 17 – Stormwater BMP adjacent to access
Road is full**

**Photo 18 – Plugged culvert at lower end of BMP in
photo # 17**