

Inspection Photos

API: 073-06189

Operator: MAGPIE OPERATING INC

Inspection Date: 4/29/2026

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing south at the beginning of the access road. The cattleguard and gate remains.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06189 | Date: 4/29/2026

Inspection Photos



Photo 2. Drone aerial photo facing southeast along the access road.



Inspection Photos



Photo 3. Drone aerial photo facing southeast toward the former tank battery site. This area has not revegetated and consists mostly of undesirable weeds.



Inspection Photos



Photo 4. Drone aerial photo facing northwest toward the former tank battery site. This area has not revegetated and consists mostly of undesirable weeds..



Inspection Photos



Photo 5. Drone aerial photo facing southeast overlooking the former tank battery site and access road.



Inspection Photos



Photo 6. Drone aerial photo facing northwest toward the location. The red arrow points to the abandoned wellsite. This area is bare of vegetation and appears to be a suspected spill causing soil impacts.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06189 | Date: 4/29/2026

Inspection Photos



Photo 7. Facing southeast at the former tank battery location. This area consists mostly of undesirable weeds.



Inspection Photos



Photo 8. There is hydrocarbon impacts at the former tank battery that have become exposed at the surface..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 9. Facing northeast toward the former wellsite. This area has no vegetation and appears to have impacted soils from a historic spill..



Inspection Photos



Photo 10. Facing south toward the surrounding reference area which consists of Blugrama dominated grassland.

