

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2026

Submitted Date:

04/24/2026

Document Number:

715204367

FIELD INSPECTION FORM

Loc ID 303169 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252588	WELL	PR	12/01/2025	GW	125-06464	PINKARD 1-17	PA

General Comment:

[SE Compliance Specialist Brian Welsh conducted a P&A Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Elevated gravel road through farm ground		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Metal fence around unit, wellhead, meter shed, HGS and water tank		
Corrective Action:		Date:	
Equipment:			
Type: Prime Mover	# 0		corrective date
Comment:	Electric motor has been removed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Electric panel has been removed		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Jensen unit has been removed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed on east side of wellhead		
Corrective Action:	Operator has 30 days to remove equipment after the well has been plugged		Date: <u>06/01/2026</u>

Type: Horizontal Separator	# 1	
Comment:	HGS on south side of meter shed	
Corrective Action:	Operator has 30 days to remove equipment after the well has been plugged	Date: 06/01/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		39.707380,-102.209310
Comment:	Fiberglass open top water tank 50% buried on north side of wellhead				
Corrective Action:	Operator has 30 days to remove tanks after the well has been plugged				Date: 06/01/2026

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 252588 Type: WELL API Number: 125-06464 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 380

Cement Volume (sx): 134 SXS

Good Return During Job: _____

Cement Type: CLASS A

Comment: BOHLER WELL SERVICE. MIRU TO 4 1/2" CSG. PUMP 134SXS CMT WITH CIRCULATION. MIRU TO BRADENHEAD, STARTED PUMPING AND FOUND THE BULL PLUG ON THE OPPOSITE SIDE WAS CORRODED AND BLOWN OUT. DUG OUT AROUND WELLHEAD TO TRY TO GET A NEW BULL PLUG PUT IN. THREADS WERE CORRODED AND NOT ABLE TO PLUG OFF THE WELLHEAD. CEMENT OPERATOR DECIDED TO COME BACK AND FINISH PLUGGING AT A LATER DATE.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404634019	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526621
715204392	Cementing equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526616