

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2026

Submitted Date:

04/24/2026

Document Number:

715204368

FIELD INSPECTION FORM

Loc ID 303076 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252411	WELL	SI	01/01/2025	GW	125-06285	DICKSON 1-22	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a P&A Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through feed yard		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Metal fence around unit, wellhead, meter shed, HGS and water tank		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 0		
Comment:	Jensen unit has been removed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Gas scrubber has been removed		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Arrow gas engine has been removed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed next to HGS		
Corrective Action:	Operator has 30 days to removed equipment from location after the well has been plugged		Date: <u>05/22/2026</u>
Type: Horizontal Separator	# 1		
Comment:	HGS next to meter shed		
Corrective Action:	Operator has 30 days to removed equipment from location after the well has been plugged		Date: <u>05/22/2026</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 252411 Type: WELL API Number: 125-06285 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 363

Cement Volume (sx): 136 SXS

Good Return During Job: YES

Cement Type: CLASS A

Comment: BOHLER WELL SERVICE MIRU TO CSG. PUMP 8 BBLS WATER TO BREAK CIRC. PUMP 136 SXS CMT WITH CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Main access to location is through the feed lot](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404634020	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526622
715204393	cementing quipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526617