

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2026

Submitted Date:

04/24/2026

Document Number:

716302229

**FIELD INSPECTION FORM**

Loc ID 333383 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282287	WELL	PR	05/09/2006	CBM	071-08660	SCREAMIN 12-29 TR	PR
282288	WELL	SI	12/01/2025	CBM	071-08661	SCREAMIN 12-29	SI

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 6: OILY WASTE IN TR WELL PRIME MOVER ENGINE SKID.		
Corrective Action:	DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002.(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.		Date: <u>04/25/2026</u>
Type	WEEDS		
Comment:	PHOTO 7: WEEDS/ VEGETATION ON AND INSIDE TANK BATTERY BERMS.		
Corrective Action:	REMOVE WEEDS/VEGETATION FROM ON AND INSIDE BERMS PER RULE 606.		Date: <u>05/24/2026</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Count	Comment	Corrective Action	Date	corrective date
Type: Bradenhead	# 2				
Comment:	BOTH ARE ACCESSABLE				
Corrective Action:					
Type: Ancillary equipment	# 4				
Comment:					
Corrective Action:					
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:					
Type: Progressive Cavity	# 2				
Comment:					
Corrective Action:					
Type: Deadman # & Marked	# 6				
Comment:					
Corrective Action:					
Type: Gas Meter Run	# 2				
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.				
Corrective Action:					

Type: Prime Mover	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.231069,-104.702324
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<a href="#">SEE HOUSEKEEPING SECTION FOR CORRECTIVE ACTION.</a>			
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 282287 Type: WELL API Number: 071-08660 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/16/2011 Annual Brhd Completed? \_\_\_\_\_  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: FORM 4 BRHD SUNDRY IS ON FILE DOC. #400682680.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 282288 Type: WELL API Number: 071-08661 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_  
 Comment: WELL LAST PRODUCED 11/1/2025.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/16/2011 Annual Brhd Completed? \_\_\_\_\_  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: FORM 4 BRHD SUNDRY IS ON FILE DOC. #400682687.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404633468	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526235</a>
716302230	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526229">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526229</a>