

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2026

Submitted Date:

05/01/2026

Document Number:

715204398

FIELD INSPECTION FORM

Loc ID 321573 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: MULL DRILLING COMPANY INC
City: WICHITA State: KS Zip: 67206-

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
OBryhim, Risa		ROBryhim@mulldrilling.com	All Inspections
Quint, Craig		craig.quint@state.co.us	
Beasley, Nolan		nolan.beasley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207332	WELL	IJ	05/12/2021	ERIW	017-06267	MULL UNIT (MCCORMICK 3) 16	AC

General Comment:

[SE Compliance Specialist Brian Welsh conducted a UIC MIT](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels around solar panel and dehydrator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 207332 Type: WELL API Number: 017-06267 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>MRRW</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>04/29/2021</u>
			AnnMTReq: <u>NO</u>

Comment:

Corrective Action: Date: _____

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: 250 Csg psi: 0 PSIG BH psi: _____

Insp. Status: Pass

Comment: API# 05-017-06267
 SGB Solutions pressure up with treat truck
 Test start Pressure
 Tbg- 250 PSIG Csg- 600 PSIG
 Pressure at 5 minutes
 Tbg- 250 PSIG Csg- 580 PSIG
 Pressure at 10 minutes
 Tbg- 250 PSIG Csg- 560 PSIG
 Pressure at 15 minutes
 Tbg- 250 PSIG Csg- 560 PSIG
 End of Test. PASS
 Submit Form 21 electronically (a copy is attached) within 30 days of MIT

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715204448	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534403