

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2026

Submitted Date:

05/01/2026

Document Number:

716302267

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
321110 \_\_\_\_\_ Beardslee, Tom \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 \_\_\_\_\_ 6 Number of Comments  
 \_\_\_\_\_ 2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: \_\_\_\_\_ 61650 \_\_\_\_\_  
 Name of Operator: MURFIN DRILLING COMPANY INC \_\_\_\_\_  
 Address: 250 N WATER ST STE 300 \_\_\_\_\_  
 City: \_\_\_\_\_ WICHITA \_\_\_\_\_ State: \_\_\_\_\_ KS \_\_\_\_\_ Zip: \_\_\_\_\_ 67202 \_\_\_\_\_

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Goodrich, Christina		cgoodrich@murfininc.com	Murfin Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206067	WELL	TA	07/06/2023	OW	009-06483	S.E. CAMPO UNIT 602	TA

**General Comment:**  
 "This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT (WELLHEAD FENCING).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.	Date:	05/15/2026
Type	TRASH		
Comment:	PHOTO 5: TRASH EAST OF LOCATION.		
Corrective Action:	REMOVE ALL TRASH ON AND AROUND LOCATION PER RULE 606.	Date:	05/15/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 206067 Type: WELL API Number: 009-06483 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL HAS BEEN P & A.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
THIS IS A FOLLOW-UP TO INSP. DOC. #710500462, CA'S HAVE BEEN ADDRESSED HOWEVER THERE ARE NEW CORRECTIVE ACTIONS, SEE HOUSEKEEPING AND ATTACHED PHOTOS FOR DETAILS.	beardslt	05/01/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302268	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535145">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535145</a>