


**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



**Unpainted and/or Paint deterioration
and areas of rust.**



**Unpainted and/or Paint deterioration
and areas of rust.**

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



**Unpainted and/or Paint deterioration
and areas of rust.**




**Unpainted and/or Paint deterioration
and areas of rust.**

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



**Unpainted and/or Paint deterioration
and areas of rust.**



**Unpainted and/or Paint deterioration
and areas of rust.**

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Rusted valves and fittings on catalytic heater.



Rusted valves and fittings on catalytic heater.

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Rusted valves and fittings on catalytic heater.



Rusted valves and fittings on catalytic heater.

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Paint deterioration and areas of rust.


**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Paint deterioration and areas of rust.

Paint deterioration and areas of rust.

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Paint deterioration and areas of rust.



Paint deterioration and areas of rust.

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Paint deterioration and areas of rust.

**TEP ROCKY MOUNTAIN LLC
FORCE-66S94W 33NWSE
Location # 324048**



Paint deterioration and areas of rust.

Paint deterioration and areas of rust.