

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2026

Submitted Date:

05/01/2026

Document Number:

701104728

**FIELD INSPECTION FORM**

Loc ID 335488 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	EG
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	EG
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	EG
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	EG
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	EG
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	EG
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	EG
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	EG
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	EG
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	EG
298077	WELL	PR	10/01/2023	GW	045-17061	SAVAGE RWF 44-26	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Stain on tank and PRV.  
Corrective Action: Clean staining from tank and PRV.  
CA Date: 05/20/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Dumpline has a cut or unlocked pad lock on shut in valve.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Stain on tank and PRV.				
Corrective Action:	Clean staining from tank and PRV.				Date: 05/20/2026

**Paint**

Condition Adequate

Other (Content)	
Other (Capacity) 80 bbls	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>298067</u>	Type: <u>WELL</u>	API Number: <u>045-17050</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298068</u>	Type: <u>WELL</u>	API Number: <u>045-17052</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298069</u>	Type: <u>WELL</u>	API Number: <u>045-17053</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298070</u>	Type: <u>WELL</u>	API Number: <u>045-17054</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298071</u>	Type: <u>WELL</u>	API Number: <u>045-17055</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298072</u>	Type: <u>WELL</u>	API Number: <u>045-17056</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298073</u>	Type: <u>WELL</u>	API Number: <u>045-17057</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298074</u>	Type: <u>WELL</u>	API Number: <u>045-17058</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298075</u>	Type: <u>WELL</u>	API Number: <u>045-17059</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298076</u>	Type: <u>WELL</u>	API Number: <u>045-17060</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298077</u>	Type: <u>WELL</u>	API Number: <u>045-17061</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104729	Flowline integrity inspection 701104728 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535493</a>