

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/26/2026

Document Number:

693809232

FIELD INSPECTION FORM

Loc ID 316813 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256809	WELL	TA	02/01/2025	GW	113-06071	ANDY'S MESA FEDERAL 16	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #16 well, API# 113-06071, Loc ID#316813, in San Miguel County, Colorado.

The well was Temporarily Abandoned

During the inspection/audit, the following compliance issues were observed:

- 1) Past due MIT to maintain SI/TA status
- 2) No tank labels on 80 bbl PBV condensate tank

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Main		
comment:	Hwy 141		
Corrective ActionL		Date:	
Type	Access		
comment:	R25 Rd		
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign or correct sign per rule 605	Date:	05/29/2026
Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:		Date:	_____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:	Dissconnected and blind flanged		
Corrective Action:		Date:	
Type:	Deadman # & Marked	# 4	
Comment:			
Corrective Action:		Date:	
Type:	Plunger Lift	# 1	
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Disconnected and blind flanged		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	400 BBLs	STEEL AST		
Comment:	Tank removed				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	PBV STEEL		38.042300,-108.632300
Comment:	No tank labels See corrective action under labels section above.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 256809 Type: WELL API Number: 113-06071 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production 05/31/2015. Last MIT to maintain SI/TA status 5/27/2020.
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42.

Corrective Action: Perform successful mechanical integrity test per Rule 417. Operator has 30 days to perform the required MIT. Date: 05/29/2026

BradenHead

Date of Last Brhd Test: 03/18/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #16 well, API# 113-06071, Loc ID#316813, in San Miguel County, Colorado.</p> <p>The well was Temporarily Abandoned</p> <p>During the inspection/audit, the following compliance issues were observed: 1) Past due MIT to maintain SI/TA status 2) No tank labels on 80 bbl PBV condensate tank</p>	browninc	04/26/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404634244	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526779
693809244	Inspection photos 4/23/2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526775