

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2026

Submitted Date:

04/27/2026

Document Number:

701104709

**FIELD INSPECTION FORM**

Loc ID 322299 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Metz, Collin		collin.metz@state.co.us	
Morris, Matthew		matthew.morris@state.co.us	
,		mark.schlagenhauf@state.co.us	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210185	WELL	PR	01/01/2026	GW	045-05080	SOUTH CANYON-FEDERAL 4	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Corrective action from 1/28/2026 inspection # 719500858: SVR vent line is open-ended. Louver has broken off of vent piping. FIRR 404538082 received 0/9/2026 with 2 photo attachments doc # 404538108 and 404538110. Operator comment: Vent Line Repaired On 4/16/2026 3 of the 7 wind turbines were found to be off their vent lines and another has fence leaned against it's turbine preventing it from turning. One of the vent line is not in the ground securely.  
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.  
Seek more permanent solution to repair and prevent continued failure.  
CA Date 5/8/2026  
Damaged paint on bottom of tank.  
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.  
CA Date 5/8/2026  
Storm water in tank berm.  
Remove and maintain berm free of storm water.  
CA Date 5/8/2026



Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210185 Type: WELL API Number: 045-05080 Status: PR Insp. Status: EG

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404635050	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7527308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7527308</a>
701104710	Flowline integrity inspection 701104709 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7527306">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7527306</a>