

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2026

Submitted Date:

04/27/2026

Document Number:

707801971

## FIELD INSPECTION FORM

Loc ID 414020	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 14 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 95960 Name of Operator: WEXPRO COMPANY Address: P O BOX 45003 City: SALT LAKE CITY State: UT Zip: 84145-				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Polk, Josette		josette.polk@enbridge.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
411959	WELL	PR	06/01/2023	GW	081-07468	B W MUSSER 31	PR
418298	WELL	SI	01/01/2025	GW	081-07617	Carl Allen Unit 37	PA
418299	WELL	PR	06/01/2023	GW	081-07618	BW MUSSER 38	PR
418306	WELL	PR	06/01/2023	GW	081-07619	B.W. MUSSER 39	PR

**General Comment:**

ECMC Inspection Report Summary  
 On Wednesday 4/1/2026, I, Inspector Scott Ramsey, conducted a routine inspection/audit on site at Wexpro Musser BWB 31, at Location # 414020 in Moffett County Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, NSO habitat, Wildlife Density habitat.  
 During this inspection the following possible compliance issues were observed:

1. Battery signage lacks information
2. Well signage lacks information
3. Random debris
4. Stored equipment
5. Some staining

Refer to photograph of observed compliance issue.  
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well signage lacks information		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery signage lacks information		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	800-341-3129/911		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Random staining inside containment and around well heads		
Corrective Action:	Remove and dispose of contaminated material properly	Date:	05/29/2026
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/08/2026
Type	STORAGE OF SUPL		
Comment:	Stored equipment		
Corrective Action:	Remove, put into service or provide proper documentation for stored equipment	Date:	05/08/2026

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks in containments		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Running and not metered		
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 411959 Type: WELL API Number: 081-07468 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<u>Producing</u>	
Corrective Action:		Date:

Facility ID: 418298 Type: WELL API Number: 081-07617 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Well was recently plugged and abandoned. For 6 on file and approved document # 404512788

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418299 Type: WELL API Number: 081-07618 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<u>Producing</u>	
Corrective Action:		Date:

Facility ID: 418306 Type: WELL API Number: 081-07619 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<u>Producing</u>	
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No storm water BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404635941	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528117</a>
707801975	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528113</a>