



ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 482194 and Remediation Project # 25606. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this inspection. Photos attached to document site conditions.

Spill/Release Point ID 491349 is located nearby and will be addressed in a separate Field Inspection Report, Document # 717100506.

Spill Name: Stromquist 4A

Spill ID: 482194

Remediation Project #: 25606

Reported Date of Discovery: 05/15/2022

Date of Inspection: 03/25/2026

Weather: Sunny, 86°F

Spill is located within or in close proximity to:

-Within the Town of Frederick

-Idaho Creek (~200 ft)

-Riverine wetland (~200 ft)

-Freshwater Pond (<100 ft)

-Within buffers for the following CPW High Priority Habitats: Bald Eagle Active Nest Site Half Mile & Bald Eagle Roost Site

-FEMA 100-Year Effective (2020) Floodplain (~100 ft)

-Residential Building Units (<150 ft)

Current site status:

-The excavation at the spill location remains open. Weeds obscure visibility of the majority of the excavation base and sidewalls.

-No work appears to have been performed on this excavation since previous Field Inspection Report (Document # 697602103, 06/06/2023). Impacts have been documented and appear to remain in situ.

-Barbed wire fencing surrounds the excavation.

-A network of monitoring wells completed as PVC stickups was observed on location.

See attached corrective actions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: Weeds obscure visibility of the majority of the excavation base and sidewalls.

Corrective Action: Comply with Rule 606. CA due date backlisted per Field Inspection Report Document # 717100378.

Date: 09/23/2025

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 482194 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

Date:

**Comment:**

**Corrective Action:**

Date:

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: The excavation at the spill location remains open. Weeds obscure visibility of the majority of the excavation base and sidewalls. Salt crusting is visible within the excavation. Groundwater has been previously documented at the base of the excavation. No work appears to have been performed on this excavation since the previous Field Inspection Report (Document # 697602103).

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. CA due date backlisted per Field Inspection Report Document # 697602103. Operator shall IMMEDIATELY resume cleanup activities at this location.

Date: 06/09/2023

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Remediation Project # 25606 was created to address the ongoing remediation associated with Spill ID 482194. The excavation at the spill location remains open. Impacts have been documented and appear to remain in situ. A network of monitoring wells completed as stickups was observed on location. Quarterly reporting is required under Remediation Project # 25606; the last Form 27 for this project was submitted 06/21/2024 (Document # 403817048).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 25606. CA due date backlisted to the date an updated Form 27 was due.

Date: 09/09/2024

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404636216	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528490">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528490</a>
717100508	ECMC Photo Log - Stromquist 4A - 03.25.2026	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7528487</a>