

Inspection Photos
Hwy52 & CR19 (G)
SPILL ID 493177



Fencing around former work area



Former excavation area

Inspection Photos
Hwy52 & CR19 (G)
SPILL ID 493177



Fencing around former work area



Fencing around former work area



Inspection Photos
Hwy52 & CR19 (G)
SPILL ID 493177



Hydrophobic oil-absorbent booms installed within Little Dry Creek adjacent to former excavation.



Hydrophobic oil-absorbent booms installed within Little Dry Creek adjacent to former excavation.



Inspection Photos
Hwy52 & CR19 (G)
SPILL ID 493177



Hydrophobic oil-absorbent booms installed within Little Dry Creek downstream of former excavation.



Hydrophobic oil-absorbent booms installed within Little Dry Creek adjacent to former excavation.

