

Inspection Photos
Wandell 2N67W/7NENE
Spill ID 491145/Remediation No 40433



Photo 1 – Open excavation. Fencing adequate.

Photo 2 – Open excavation. Fencing adequate.

Inspection Photos
Wandell 2N67W/7NENE
Spill ID 491145/Remediation No 40433



Photo 3 – Open excavation.



Photo 4 – Open excavation. Groundwater beginning to seep in.

Inspection Photos
Wandell 2N67W/7NENE
Spill ID 491145/Remediation No 40433



Photo 1 – Former wellhead location.



Photo 6 – Open excavation.