

Inspection Photos  
Johnson 1 Flowline  
Spill ID 485936/Remediation No 34666



Photo 1 – Location photo



Photo 2 – Spill area. Fencing down around open excavation.

Inspection Photos  
Johnson 1 Flowline  
Spill ID 485936/Remediation No 34666



ECMC Environmental Inspection  
40.10321, -104.96822, 1488.4m, 50°  
04/28/2026 02:46:01 PM



ECMC Environmental Inspection  
40.10322, -104.9682, 1488.7m, 46°  
04/28/2026 02:46:08 PM

**Photo 3 – Fencing down around open excavation. Stormwater waddles have degraded and become trash. Monitoring wells present around open excavation (red).**

**Photo 4 – Open excavation. Excavation visibility largely obscured by weeds. Groundwater present in open excavation.**

Inspection Photos  
Johnson 1 Flowline  
Spill ID 485936/Remediation No 34666



**Photo 5 – Open excavation. Excavation visibility largely obscured by weeds. Groundwater present in open excavation.**

**Photo 6 – Groundwater in open excavation. Repaired flowline through open excavation largely obscured by weeds (yellow).**

Inspection Photos  
Johnson 1 Flowline  
Spill ID 485936/Remediation No 34666



**Photo 7 – Stormwater waddles have degraded and become trash (green).**



**Photo 8 – Excavation previously observed at wellhead has been backfilled.**