

**Inspection Photos
Paul Heinze 1 Flowline
Spill ID 479232 & 480128/Remediation No 18594**



Photo 1 – Open excavation. Flowline runs through open excavation. No groundwater present. Weeds on excavation sidewalls.

Photo 2 – Flowline Running through open excavation. Weeds on excavation sidewalls.

Inspection Photos
Paul Heinze 1 Flowline
Spill ID 479232 & 480128/Remediation No 18594



Photo 3 – Contaminated stockpile remains on location.

Photo 4 – Contaminated stockpile remains on location. Weeds growing through stockpile. Holes present in stockpile liner.