

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2026

Submitted Date:

05/04/2026

Document Number:

713302634

FIELD INSPECTION FORM

Loc ID: 309857 Inspector Name: Kester, Michael On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
400	WELL	TA	05/12/2020	GW	123-25471	DINNER E 14-5	TA

General Comment:

well site inspection

Location

Lease Road:			
Type	Other		
comment:	ag field, walk in		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Missing Sign not posted or information inaccurate at well		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 06/04/2026

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 400 Type: WELL API Number: 123-25471 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Form 6A on file doc 403118488, 8-16-2022 well head disconnected with fittings plugged

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/19/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents, conducted on-site inspection</p> <p>Location: Dinner E14-5 Operator: Noble API#: 123-25471 County: Weld</p> <p>While there, I observed well site with Form 6A on file doc 403118488, 8-16-2022 well head disconnected with fittings plugged, During this inspection the following possible compliance issues were observed:</p> <p>Sign Missing, Rule 605d, corrective action date 6-4-2026 photo attached</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	05/04/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302635	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7536687