

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

02/17/2025

Document Number:

404049430

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10575 Contact Person: James Miller
Company Name: 8 NORTH LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmillier@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 460851 Location Type: Production Facilities
Name: Kane #20-10 Number:
County: BOULDER
Qtr Qtr: SENW Section: 20 Township: 1N Range: 69W Meridian: 6
Latitude: 40.036435 Longitude: -105.142498

Description of Corrosion Protection

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 461294 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 321263 Location Type: Well Site   
Name: KANE-61N69W Number: 20SENW  
County: BOULDER No Location ID  
Qtr Qtr: SENW Section: 20 Township: 1N Range: 69W Meridian: 6  
Latitude: 40.038310 Longitude: -105.143410

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375  
Bedding Material: Native Materials Date Construction Completed: 12/29/1981  
Maximum Anticipated Operating Pressure (PSI): 245 Testing PSI: 245  
Test Date: 03/13/2018

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 12/16/2024

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).  
(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the KANE 20-10 (05-013-06048) was abandoned in place as per Rule 1105.d and verified by a third party. See attached.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline was abandoned in place: 01306048FL: services the Kane 20-10 (05-013-06048)  
Third party verification attached.  
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.  
Signed: \_\_\_\_\_ Date: 02/17/2025 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:  \_\_\_\_\_ Director of ECMC Date: 5/4/2026

## CONDITIONS OF APPROVAL, IF ANY LIST

**COA Type**

**Description**

--	--

### ATTACHMENT LIST

**Att Doc Num**

**Name**

404049430	Form44 Submitted
404049442	THIRD PARTY VERIFICATION
404095896	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 3 Files

### General Comments

**User Group**

**Comment**

**Comment Date**

Engineer	Pressure was submitted with pre-abandonment notice Doc#403945860	05/04/2026
Engineer	County added.	05/04/2026

Total: 2 comment(s)