

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/28/2026

Document Number:

693809237

**FIELD INSPECTION FORM**

Loc ID 316810 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10841  
Name of Operator: AMERICAN HELIUM LLC  
Address: 23501 CINCO RANCH BLVD, B244  
City: KATY State: TX Zip: 77494

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232871	WELL	SI	06/01/2024	GW	113-06060	COCKLEBUR DRAW UNIT 3	TA
288565	WELL	SI	11/01/2024	GW	113-06228	COCKLEBUR DRAW 4	TA

**General Comment:**

[ECMC Inspection/Audit Report Summary](#)

On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Cocklebur Draw Unit #3 well, API# 113-06060, Loc ID#316810, in San Miguel County, Colorado.

The well was Temporarily Abandoned

During the inspection/audit, the following compliance issues were observed:

- 1) MIT due to maintain SI/TA staus

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	Hwy 141		
Corrective Action			Date:
Type	Access		
comment:	28T Rd & Pony Draw Gas Well Rd		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign at location entrance		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe barricade		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line	# 1		corrective date
Comment:	Production flowline to location ID#311866 approx. 0.5 NW		
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 232871 Type: WELL API Number: 113-06060 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last Production 04/30/2024.  
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42.

Corrective Action: Perform successful mechanical integrity test per Rule 417. Operator has 30 days to perform the required MIT. Date: 05/29/2026

**BradenHead**

Date of Last Brhd Test: 04/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Bradenhead test completed per CA from inspection Doc#693807796 on 10/10/2024.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288565 Type: WELL API Number: 113-06228 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: See Inspection Doc#693809236 on 4/23/2026.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: See Inspection Doc#693809236 on 4/23/2026.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404638166	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530142</a>
693809249	Inspection photos 4/23/2026	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530138</a>