

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2026

Submitted Date:

04/28/2026

Document Number:

719001840

**FIELD INSPECTION FORM**

Loc ID 326147 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215946	WELL	PR	04/12/2000	CBM	067-07551	HUBER-LOBATO 1-26	PR

**General Comment:**

Inspection Report Summary  
On 4/28/26 | Inspector Charles Garcia conducted an on-site inspection.  
Location: HUBER-LABATO 1-26  
API# 067-07551  
Operator: HILLCORP ENERGY COMPANY  
County: LaPlata  
All prior CA's still stand.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	WELL SIGN IN FRONT OF SEPARATOR		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		Date:
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	EAST SIDE OF LOCATION UNUSED EQUIPMENT AND 5 GAL LEAKING BUCKET SEE LOCATION PICTURES		
Corrective Action:	Unnecessary equipment COMLPY WITH RULE 606		Date: 05/13/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	SOUND WALLS		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Other # 1			
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Flow Line # 1			
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment # 2			
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	LEAK ON ENGINE FOR PRIME MOVER HAS CAUSED OIL TO LEAK ON BOTH SIDES OF ENGINE SKID		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PRIME MOVER SKID rule 1002.f	Date:	05/05/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215946 Type: WELL API Number: 067-07551 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/07/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>EAST SIDE OF LOCATION UNUSED EQUIPMENT AND 5 GAL BUCKET LEAKING OIL                      SEE LOCATION PICTURES                      Unnecessary equipment COMPLY WITH RULE 606                      LEAK ON ENGINE FOR PRIME MOVER HAS CAUSED OIL TO LEAK ON BOTH SIDES                      OF ENGINE SKID                      MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND                      PRIME MOVER SKID rule 1002.f</p>	garciacr1	04/28/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404638124	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529991</a>
719001859	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529987</a>