

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2026

Submitted Date:

04/28/2026

Document Number:

719501070

FIELD INSPECTION FORM

Loc ID 312578 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 13 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wang, Jian		jian.wang@state.co.us	
Energy, Vision		mollieo@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221954	WELL	SI	01/01/1984	GW	077-08556	CAMP GULCH UNIT-FEDERAL 3-22-8-103	SI

General Comment:

This is a field audit of the location, scout card, and related documents.

On 4/21/2026 at approximately 14:35, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/22NESE at Location ID #312578 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Storage tank on location is unused equipment.		
Corrective Action:	Remove unused equipment from location.	Date:	05/29/2026
Type	WEEDS		
Comment:	Weeds are present across location.		
Corrective Action:	Remove weeds from location.	Date:	05/06/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter house is unsecured and poses a wildlife entry hazard.		
Corrective Action:	Comply with CECMC wildlife safety rules.	Date:	05/04/2026

Type: Dehydrator	# 1	
Comment:	Dehydrator is unsecured and poses a wildlife entry hazard.	
Corrective Action:	Comply with CECMC wildlife safety rules.	Date: 05/04/2026
Type: Horizontal Heated Separator	# 1	
Comment:	Wildlife entry hazard on separator.	
Corrective Action:	Comply with CECMC wildlife safety rules.	Date: 05/04/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<100 BBLS	Open Top		
Comment:	Storage tank is corroded in multiple areas and open to wildlife.				
Corrective Action:	Comply with CECMC wildlife safety rules.				Date: 05/04/2026

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment is installed at storage tank. Tank is disconnected, empty, and is unused equipment. Refer to Housekeeping Corrective Action.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221954 Type: WELL API Number: 077-08556 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced January 2004. Last MIT performed 6/26/2012. Well is overdue for MIT.

Corrective Action: Comply with CECMC Mechanical Integrity Testing requirements. Date: 10/11/2024

BradenHead

Date of Last Brhd Test: 10/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last Bradenhead test performed 4/9/2026.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <ul style="list-style-type: none"> 1) Weeds are present across location 2) Unused storage tank on location 3) Wildlife entry hazards at gas meter house, dehydrator, separator, and storage tank 4) Well is overdue for Mechanical Integrity Testing <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	04/28/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404638125	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529992
719501071	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7529990