



QB ENERGY OPERATING LLC BENTLEY-67S95W 11SWSE Facility # 324168



**QB ENERGY OPERATING LLC
BENTLEY-67S95W 11SWSE
Facility # 324168**



East tank was repaired with a screw. Another seep has shown up within inches of the last seep.



East tank was repaired with a screw. Another seep has shown up within inches of the last seep.

**QB ENERGY OPERATING LLC
BENTLEY-67S95W 11SWSE
Facility # 324168**



No OOSLAT tag